

4- Conductor Resistance

- * Measure One meter of the conductor after preparing it, using the Ohmmeter – the conductor resistance
- * Calculate the conductor resistance at 20° C using temperature correction factor
- * The value should not exceed the standard values in tables (2) and (3) for IEC 60228

