

7- Heat Resistance

- * Pick a sample wind around a cylinder in small steps , Put it in the Oven at 150° C for One Hour
- * After that get it out of the Oven and leave it until it reaches the room temperature
- * Disassemble for testing
- * The sample passes the test if there is no cracks

